


EVACUATION FROM LIFT - AFTER UP TRAVEL



UNINTENDED MOVEMENT WITH DOORS OPEN

EVACUATION FROM LIFT AFTER DOWN TRAVEL

